



# HORIZONTAL MEASURING INSTRUMENTS



## High Precision Calibration and Setting



Calibration  
of plain and  
thread  
ring gauges



Calibration  
of plain and  
thread  
plug gauges



Setting  
of large  
gauges



Large  
micrometer  
control